



2. Place the correct frame from the base (First, insert screws into the threaded holes of the frame and base for preliminary alignment, then progressively tighten each screws sequentially to achieve uniform tension distribution.)





Installation instruction




DT-009 Installation

The number of people needed for installation: 2


- Please read the manual carefully before installing this product. And strictly follow the installation process
- ② Please take good care of this manual for your next installation
- Note: Before installation, screw all the screws to 1/2 of the length of the installation. After all screws are half screwed in, tighten them all together.

Parts list		On a red ribbon are furniture installation accessories			
Serial number	Shape	Name	Quantity required for installation	Spare quantity	
A	9	Hexagon Socket Machine Screws (M8*45mm)	4	0	
В		Hexagon Socket Machine Screws (M8*15mm)	4	2	
С	0	Gasket	8	2	
D	Bun	Self-Drilling Screw(M4*15mm)	0	14	
Е		Mechanical Adjustment Foot	0	2	
F		Wrench	1	0	
G					

3. Place the tabletop on the frame, Allen screws and spacers, and tighten the Allen screws with a wrench.




4. Installation Completed (If the product is unstable or wobbles, please adjust the adjustable feet at the bottom of the product to ensure it is level with the ground.)





Installation instruction



DT-009 Installation

The number of people needed for installation: 2

- Please read the manual carefully before installing this product. And strictly follow the installation process
- Please take good care of this manual for your next installation
- 3 Note: Before installation, screw all the screws to 1/2 of the length of the installation. After all screws are half screwed in, tighten them all together.

)					
Parts list		On a red ribbon are furniture installation accessories			
Serial number	Shape	Name	Quantity required for installation	Spare quantity	
A	9	Hexagon Socket Machine Screws (M8*45mm)	4	0	
В		Hexagon Socket Machine Screws (M8*15mm)	4	2	
С	0	Gasket	8	2	
D	Boo	Self-Drilling Screw(M4*15mm)	0	14	
Е		Mechanical Adjustment Foot	0	2	
F		Wrench	1	0	
G					